

HISTORIC AMERICAN ENGINEERING RECORD

Index to Photographs

HAER
WIS,
70-OSH,
1-

Oshkosh Grass Matting Company
(Deltax Company)
35 Wisconsin Street
Oshkosh
Winnebago County
Wisconsin

HAER No. WI-11

Documentation: 26 exterior photos (1984)
5 interior photos (1984)
4 historic photos (date unknown)
28 data pages (1984)

NOTE: Photographs were taken by Carl Acker, photographer, March 1984

WI-11-1	VIEW OF BUILDINGS 4, 7. 3B, 3A, 3, LOOKING WEST FROM CRANE.
WI-11-2	VIEW OF BUILDINGS 2A, 6A, 6B, LOOKING EAST FROM CRANE.
WI-11-3	VIEW OF BUILDINGS 4, 7, 2, 2A TO THE LEFT, BUILDING 3 TO THE RIGHT, LOOKING WEST FROM WISCONSIN AVENUE.
WI-11-4	VIEW OF EAST SIDE OF BUILDING 4 AND SOUTH SIDE OF BUILDING 3.
WI-11-5	NORTHEAST SIDE OF BUILDING 4.
WI-11-6	VIEW OF EAST SIDE OF BUILDING 4.
WI-11-7	VIEW OF SOUTHEAST SIDE OF BUILDING 4.
WI-11-8	VIEW OF BUILDING, LOOKING NORTHWEST FROM WISCONSIN AVENUE.
WI-11-9	VIEW OF SOUTH SIDE OF BUILDINGS 6A, 6, 4A, 4 (left to right), LOOKING NORTHWEST FROM WISCONSIN AVENUE BRIDGE.
WI-11-10	VIEW OF SOUTH SIDE OF BUILDINGS 6A, 6, 4A, 4 (left to right), LOOKING NORTHEAST FROM FOX RIVER.
WI-11-11	VIEW OF WEST SIDE OF BUILDINGS 6A & 6B. PORTION OF SOUTH WALL OF BUILDING 2A ON FAR LEFT.
WI-11-12	VIEW OF NORTH SIDE OF BUILDINGS 3, 3A, 3B (left to right), LOOKING SOUTH.
WI-11-13	VIEW OF BUILDINGS 3, 3A, 3B, 2A, 6B (left to right), LOOKING SOUTHEAST.

Oshkosh Grass Matting Company
(Delttox Complex)
HAER No. WI-11
Index to Photographs
(Page 2)

HAER
WIS
70-00H,
1-

- WI-11-14 VIEW OF BUILDINGS 3B, AND 2A (left to right), LOOKING EAST
- WI-11-15 VIEW OF OPEN AREA BETWEEN 2A and 7, LOOKING EAST TOWARD BUILDING 7. TOWER ON LEFT IS SMOKESTACK ON BUILDING 1.
- WI-11-16 VIEW OF LARGE OPEN AREA, LOOKING EAST. BUILDINGS 2A, 1, 7, 6 (left to right).
- WI-11-17 VIEW OF LARGE OPEN AREA, LOOKING NORTHWEST. SOUTH SIDE OF BUILDINGS 2A, 2 (left to right).
- WI-11-18 VIEW OF LARGE OPEN AREA OF BUILDINGS 2, 1, 7 (left to right), LOOKING NORTHEAST.
- WI-11-19 VIEW OF LARGE OPEN AREA OF BUILDINGS 6, 2A, 1 (left to right), LOOKING WEST.
- WI-11-20 VIEW OF SMALL OPEN AREA OF BUILDINGS 7A, 7, 5 (left to right), LOOKING NORTH.
- WI-11-21 VIEW OF SMALL OPEN AREA OF BUILDINGS 7, 4 (left to right), LOOKING NORTHEAST.
- WI-11-22 VIEW OF SMALL OPEN AREA OF WEST SIDE OF BUILDING 4, NORTH SIDE OF BUILDING 5, AND EAST WALL OF BUILDING 7, LOOKING SOUTH.
- WI-11-23 VIEW OF EAST SIDE OF BUILDING 9.
- WI-11-24 VIEW OF SOUTH WALL OF BUILDING 9 AND BUILDINGS 6B, 6A IN REAR, LOOKING EAST.
- WI-11-25 VIEW OF WEST SIDE OF BUILDING 9.
- WI-11-26 VIEW OF NORTH SIDE OF BUILDING 9, BUILDING 6A IS ON THE LEFT.
- WI-11-27 VIEW IN BUILDING 1, LOOKING WEST.
- WI-11-28 VIEW OF UPPER FLOOR OF BUILDING 1, LOOKING NORTHEAST.
- WI-11-29 VIEW IN BUILDING 4, LOOKING SOUTH.
- WI-11-30 VIEW IN BUILDING 4, LOOKING SOUTHEAST.
- WI-11-31 VIEW IN BUILDING 1, LOOKING WEST.
- WI-11-32 PHOTOCOPY OF INTERIOR VIEW OF OFFICE (Photographer and date unknown).

Oshkosh Grass Matting Company
(Delttox Complex)
HAER No. WI-11
Index to Photographs
(Page 3)

WI-11-33 PHOTOCOPY OF DELTOX GRASS RUG FLOAT. Photographer and date
unknown.

WI-11-34 PHOTOCOPY OF INTERIOR VIEWS OF WAREHOUSE. Photographer and date
unknown.

WI-11-35 PHOTOCOPY OF GRASS RUGS. Photographer and date unknown.